



**Model: NDP-25BVH-PP**  
**Part # 854223 - NPT**  
**Part # 854225- Flange**



Yamaha America, Inc.  
 955 East Algonquin Rd  
 Arlington Heights, IL 60005  
 Phone: 847.631.9200  
 Fax: 847.631.9273

02\_2014

Parts Breakdown

Reference			
No.	Description	Q'ty	Part No.
1	O-ring	4	643042
2	Valve Stopper	4	780141
3	Ball	4	773127
4	Valve Seat	4	780139
5	O-ring	4	643041
6	Diaphragm	2	771363
7	Center Disk	2	716258
7T	N/A	-	-
8	Plain Washer	2	716259
9	Out Chamber	2	780136
12	O-ring	2	640154
13	Tie Rod	4	710207
14	Bolt	12	683541
15	Body Assembly	1	804604
16	Center Rod	1	710271
18	Cushion	2	771054
19	Manifold - NPT	2	780057
19	Manifold - Flange	2	780212
20	Valve Body Assembly	1	804608
21	Bolt	4	686031
22	Ball Valve	1	682772
24	Gasket	1	772848
25	Silencer	1	804697
26	Bolt	4	621153
27	Nut with Flange	4	686032
28	Pump Base	2	771749
29	Cushion	4	770551
30	Center Disk	2	780127
30T	N/A	-	-
31T	N/A	-	-
32	Nut	12	683635
33	Spring Lock Washer	12	681300
34	Plain Washer	12	631329
35	Accessory Tool	2	771244
36	Nut with Flange	12	686033
37	Spring Lock Washer	12	680257
38	Plain Washer	12	631330

Body Assembly - 804604			
Reference			
No.	Description	Q'ty	Part No.
15-1	Body	1	772929
15-2	Throat Bearing	2	772931
15-3	Packing	2	685414
15-4	O-ring	2	685276
15-5	Valve Seat	2	772932
15-6	O-ring	2	640009
15-7	Pilot Valve Assembly	2	802360
15-8	Spring	2	708666
15-9	Spring Seat	2	772948
15-10	Tapping Screw	13	686030
15-11	O-ring	1	640132
15-12	Bushing	1	772933

Repair Kits			
K25-VH-PP Liquid Side Repair Kit			
No.	Description	Q'ty	Part No.
1	O-ring	4	643042
3	Ball	4	773127
5	O-ring	4	643041
6	Diaphragm	2	771363
12	O-ring	2	640154
K225-AP Air Side Repair Kit			
18	Cushion	2	771054
15-2	Throat Bearing	2	772931
15-3	Packing	2	685414
15-4	O-ring	2	685276
15-5	Valve Seat	2	772932
15-6	O-ring	2	640009
15-7	Pilot Valve Assembly	2	802360
15-8	Spring	2	708666
15-9	Spring Seat	2	772948
15-11	O-ring	1	640132
15-12	Bushing	1	772933
20-2	O-ring	1	640002
20-4	O-ring	2	640043
20-5	Packing	1	771241
20-6 seal	Seal Ring	5	771053
20-7-*1	O-ring	6	686029
20-9	Cushion	1	771914

Valve Body Assembly - 804608			
Reference			
No.	Description	Q'ty	Part No.
20-1	Rest Button	1	772991
20-2	O-ring	1	640002
20-3	Cap A	1	772946
20-4	O-ring	2	640043
20-5	Packing	1	771241
20-6	C Spool Valve Assy.	1	802400
20-6 seal	Seal Ring	5	771053
20-7	Sleeve Assembly	1	804609
20-7-*1	O-ring	6	686029
20-8	Valve Body Assembly	1	832903
20-9	Cushion	1	771914
20-10	Cap B	1	772947

Yamada America, Inc.  
955 East Algonquin Rd  
Arlington Heights, IL 60005  
Phone: 847.631.9200  
Fax: 847.631.9273  
www.yamadapump.com